ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0609, W0607, W0310, W0603, W0611, W0334, W0605	Vydhi Hospital Main Rd, NA, Chikkanna Lyt 4th Crs, R H B Colony, 5th Crs	Thirumalangara Main road 4th and 5th Cross Road
Segment No.	**Total Length (m)**	
3/C-W0609/S101241	668.02	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	302.77	77.562318	13.100837	77.561250	13.098308	W0611	W0310
2	72.04	77.560934	13.098392	77.561540	13.098125	W0607	W0615
3	144.29	77.561465	13.099630	77.560960	13.098423	W0310	W0334
4	148.92	77.562033	13.100942	77.561508	13.099698	W0611	W0334

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Asphalting to Roads and Improvements to Drain in Thirumalangara Main road 4th and 5th Cross Roads in ward no 03 Yelahanka Satellite Town Sub division	5000000	2017
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Asphalting to Roads and Improvements to Drain in Thirumalangara Main road 4th and 5th Cross Roads in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone	003-17-000006
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE (YNK.D) /WO/138/2017 -18	31/03/2017	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/04/2017	29/04/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

KRIDL

Phone No.

9449863065

E-Mail ID

0.00

Field Inspection Details

Number of Trees

18

Any Other Information

Name

CHANDRAKANTH

Date of Inspection

24/05/2017

Remarks

COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Alluru **Street ID:** W0609, W0607, W0310,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	24/05/2017	23/06/2017	COMPLETED
SE	VASU K M	24/05/2017	23/06/2017	COMPLETED
EE	VASU K M	24/05/2017	23/06/2017	COMPLETED
AEE	ASHOK	24/05/2017	23/06/2017	COMPLETED
AE	CHANDRAKANTH	24/05/2017	23/06/2017	COMPLETED
AE	CHANDRAKANTH	24/05/2017	23/06/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0609, W0607, W0310, W0603,